C-A Unreviewed Safety Issue (USI) Form

Title of USI: Addition of RHIC ODH Fans

Description of USI (use attachments if necessary):

Additional/modified ODH fans have been added to RHIC. All new/modified fans cause the affected building ventilation flow rate to increase, thus the current SAD ODH analyses are more conservative.

Building 1004B – 3rd fan added with 28,800 CFM capacity

Building 1010A - replaced the original two 11,000 CFM fans with two 30,500 CFM fans

Building 1012A - replaced one of the original 11,000 CFM fans with a fan rated at 22,900 CFM.

Title and Date of Relevant SAD: RHIC SAD (12/30/99) and USI dated 4/19/00, Discovery of ODH Calculation Error.

Committee Chair or ESHQ Division Head must initial all items. Leave no blanks:

ITEM	APPLIES	DOES NOT APPLY
Decision to not revise the current SAD and/or ASE at this time:	BUK	
The hazard associated with the proposed work or event is covered within an existing SAD and/or ASE.	Sél	
SAD Title and Date: RHIC SAD 12/30/99.		
This Form and attachments, if necessary, shall be used to document the USI until the next revision of the appropriate SAD.	JUL	
Decision to submit a revised SAD and/or ASE to the BNL ESH Committee:		Dell
The hazard associated with the proposed work is not appropriately included in an SAD.		Den

Pay Karol	7/6/01
Signature of C-A Committee Chair or C-A ESHQ Division Head	Date
Signature of C-A Associate Chair for ESHQ	7-6-01 Date